



1. For seams assembled with GenFlex G-400 Seam Adhesive, a bead of GenFlex Edge Caulk is required on all exposed edges, following a pre-cleaning of the seam area with GenFlex Cleaner.



**Field Fabricated
Hot Stack Flashing**

Detail #: E-7.06

EPDM Systems