



1. When using GenFlex Seam Tape and GenFlex Bar Cover Tape, first clean the membrane with GenFlex Cleaner. Then apply GenFlex Primer.
2. For GenFlex Seam Tape end lap splice, refer to Detail E-6.12.



10/06

Seam Tape Application	Detail #: E-6.01	EPDM Systems
------------------------------	-------------------------	---------------------