



GenFlex Fasteners and Anchor or Poly Bar Centered over **Solid Line**. See Detail T-6.05. GenFlex Fasteners and Seam Plates or Anchor Bar Centered Over Spacing Dots. See Detail T-6.05. Refer to the GenFlex web site for the most current GenFlexEZ TPO Fastening Matrix for fastener spacing requirements.

\*Position adjacent membrane panels on the factory-applied dashed reference line, and install membrane securement (anchor or poly bar only) as required, centered directly over Adhered and Ballasted reference line **NOT OVER FASTENER DOTS**. This allows sufficient membrane on each side of the bar to achieve a minimum 1" (25 mm) hot air weld on each side.



<b>Duel Weld Seam</b>	
EZ TPO Systems	ACCEPTABLE SYSTEMS: Mechanically Attached Systems

<b>MAXIMUM WARRANTY: 20 Years</b>	
ISSUE / REVISION DATE: 10-27-2015	<b>DETAIL NO. EZ-6.03</b>
NOT TO SCALE	