



SEAM EDGE TREATMENT AT LAP SPLICE



- NOTE:
1. REFER TO GENFLEX™ WEBSITE FOR THE MOST CURRENT INFORMATION.
 2. ALLOW GENSPLICE ADHESIVE TO FLASH OFF BEFORE APPLYING EDGE CAULK.
 3. USE GENPRIME TO CLEAN AND PRIME EPDM MATING SURFACE PRIOR TO INSTALLATION OF PEEL & STICK PRODUCTS.
 4. EXTRA CLEANING IS REQUIRED AT FACTORY SPLICE AREAS AND OTHER AREAS WHERE EXCESS DUSTING AGENTS MAY HAVE ACCUMULATED.

SEAM EDGE TREATMENT FOR PEEL & STICK PRODUCTS



**PEEL & STICK ADHESIVE LAP SPLICE WITH
6" PEEL & STICK COVER TAPE**

ACCEPTABLE SYSTEMS: EZ EPDM PEEL & STICK™ SELF ADHERED

MAXIMUM WARRANTY: 20 Years

ISSUE / REVISION
DATE:

07/28/2023

DETAIL NO.

EZE-PS-LS-05

(800) 443-4272 www.genflex.com

NOT TO SCALE