



- NOTE:
1. REFER TO GENFLEX™ WEBSITE FOR THE MOST CURRENT INFORMATION.
 2. REMOVE ALL EXISTING FLASHING, LEAD, ETC. PIPE SURFACE MUST BE FREE OF ALL RUST, GREASE, INSULATION, ETC.
 3. PIPE MUST BE ANCHORED TO ENSURE STABILITY.
 4. APPLY EDGE CAULK AROUND ENTIRE PERIMETER OF FLASHING. REFER TO EZE-PS-LS-09 FOR SEAM EDGE TREATMENT.



PENTRATION (HOT STACK) WITH FIELD FABRICATED FLASHING

ACCEPTABLE SYSTEMS: EZ EPDM PEEL & STICK™ SELF ADHERED

MAXIMUM WARRANTY: 20 Years

ISSUE / REVISION DATE:
07/28/2023

DETAIL NO.
EZE-PS-P-04

(800) 443-4272 www.genflex.com

NOT TO SCALE