
NOTE:

- 1. REFER TO WWW.GENFLEX.COM FOR MOST CURRENT INFORMATION.
- 2. REFER TO DETAILS MB-LS-15, MB-LS-16 & MB-LS-17 FOR APPROPRIATE LAP SEALING OPTIONS.



GENFLEX	INSIDE CORNER		MAXIMUM WARRANTY: 20 Years	
			ISSUE / REVISION DATE:	DETAIL NO.
	GENFLEX	ACCEPTABLE SYSTEMS: MODIFIED BITUMEN	05/07/2025	MB-C-2
GENFLEX: (800) 443-4272 www.genflex.com		NOT TO SCALE		